


Salt River Ecosystem Restoration Project

Photo Monitoring – 2018



Annual photo monitoring of the restored restoration area is required for 10 years for each constructed phase of the project. The following photographs depict the restoration areas at multiple established photo points located on the implemented portions of the Salt River Ecosystem Restoration Project footprint. This area constitutes the construction extent for the Salt River Ecosystem Project up to year 2018. Photo points 145 to 192 are in an area restored in 2013. Photo points 115, 114, 109, and 110 are in an area restored in 2014. Photo point 107 has been photographed for three years and is located in an area that does not depict restoration efforts or benefits, thus this point has been abandoned. Photo points 103, 104, and 105, are in an area restored in 2017.

Given the large amount of annual photos, photos provided in this report are a selection of years. However, 2018 photos will be provided for all points if available.

Photo Point 145



PP145 – West – July 2011



PP145 – West – Nov 2013



PP145 – West – Nov 2015



PP145 – West – Oct 2018



PP145 – East - July 2011



PP145 – East – Nov 2013



PP145 – East – Nov 2015



PP145 – East – Oct 2018



PP145 – SW – July 2011



PP145 – SW – Nov 2013



PP145 – SW – Nov 2015



PP145 – SW – Oct 2018

Photo Point 151



PP151 – South – August 2011



PP151 – South – Nov 2013



PP151 – South – Nov 2015



PP151 – South – Oct 2018



PP151 – S to Cypress – Jul 2011



PP151 – S to Cypress – Nov 2013



PP151 – S to Cypress – Nov 2015



PP151 – S to Cypress – Oct 2018



PP151 – West – July 2011



PP151 – West – Nov 2013



PP151 – West – Nov 2015



PP151 – West – Oct 2018



PP151 – To Old Levee – Jul 2011



PP151 - To Old Levee – Nov 2013



PP151 - To Old Levee – Nov 2015



PP151 - To Old Levee – Oct 2018

Photo Point 159



PP159 – SW Tidegates – July 2011



PP159 – SW Tidegates – Nov 2013



PP159 – SW Tidegates – Nov 2015



PP159 – SW Tidegates – Oct 2018



PP159 – SW Pine – July 2011



PP159 – SW Pine – Nov 2013



PP159 – SW Pine – Nov 2015



PP159 – SW Pine – Oct 2018



PP159 – NW – July 2011



PP159 - NW – Nov 2013



PP159 - NW – Nov 2015



PP159 - NW – Oct 2018

Photo Point 160



PP160 – NE – July 2011



PP160 – NE – Nov 2013



PP160 – NE – Nov 2015



PP160 – NE – Oct 2018



PP160 – NW – July 2011



PP160 – NW – Nov 2013



PP160 – NW – Nov 2015



PP160 – NW – Oct 2018



PP160 – West – July 2011



PP160 – West – Nov 2013



PP160 – West – Nov 2015

NO IMAGE
AVAILABLE

PP160 – West – Oct 2018



PP160 – SE – July 2011



PP160 – SE – Nov 2013



PP160 – SE – Nov 2015



PP160 – SE – Oct 2018

Photo Point 163



PP163 – NW – July 2011



PP163 – NW – Nov 2013



PP163 – NW – Nov 2015



PP163 – NW – Oct 2018



PP163 – SW – July 2011



PP163 – SW – Nov 2013



PP163 – SW – Nov 2015



P163 – SW – Oct 2018



PP163 – SE – July 2011



PP163 – SE – Nov 2013



PP163 – SE – Nov 2015



PP163 – SE – Oct 2018



PP163 – NE – July 2011



PP163 – NE – Nov 2013



PP163 – NE – Nov 2015



PP163 – NE – Oct 2018

Photo Point 189 (No site access in 2015 to 2018)



PP189 – Dwn Strm – Sept 2011



PP189 – Dwn Strm – Nov 2013



PP189 – Dwn Strm – Nov 2014

NO IMAGE
AVAILABLE

PP189 – Dwn Strm – Oct 2018



PP189 – NE – Sept 2011



PP189 – NE – Nov 2013



PP189 – NE – Nov 2014

NO IMAGE
AVAILABLE

PP189 – NE – Oct 2018



PP189 – East – Sep 2011



PP189 – East – Nov 2013



PP189 – East – Nov 2014

NO IMAGE
AVAILABLE

PP189 – East – Oct 2018



PP189 – SE – Sept 2011



PP189 – SE – Nov 2013



PP189 – SE – Nov 2014

NO IMAGE
AVAILABLE

PP189 – SE – Oct 2018

Photo Point 192 (No site access in 2015 or 2017)



PP192 – North – Sept 2011



PP192 – North – Nov 2013



PP192 – North – Nov 2014

NO IMAGE
AVAILABLE

PP192 – North – Oct 2018



PP192 – NW – Sept 2011



PP192 – NW – Nov 2013




PP192 – NW – Nov 2014

NO IMAGE
AVAILABLE

PP192 – NW – Oct 2018



PP192 – SE – Sept 2011



PP192 – SE – Nov 2013



PP192 – SE – Nov 2014

NO IMAGE
AVAILABLE

PP192 – SE – Oct 2018

Photo Point 115



PP115 – Reas Crk – Jul 2011



PP115 – Reas Crk – Nov 2014



PP115 – Reas Crk – Nov 2015



PP115 – Reas Crk – Feb 2020

Photo Point 114



PP114 – W Toste NE – Jul 2011



PP114 – W Toste NE – Nov 2014




PP114 – W Toste NE – Nov 2015



PP114 – W Toste NE – Nov 2018

Photo Point 109



PP109 – Dillon Br S – Jul 2011



PP109 – Dillon Br S – Nov 2014



PP109 – Dillon Br S – Nov 2015



PP109 – Dillon Br S – Feb 2020



PP109 – Dillon Br W – Jul 2011



PP109 – Dillon Br W – Nov 2014



PP109 – Dillon Br W – Nov 2015



PP109 – Dillon Br W – Feb 2020



PP109 – Dillon Br N – Jul 2011



PP109 – Dillon Br N – Nov 2014



PP109 – Dillon Br N – Nov 2015



PP109 – Dillon Br N – Feb 2020



PP109 – Dillon Br Down – Jul 2011



PP109 – Dillon Br Down – Nov 2014



PP109 – Dillon Br Down – Nov 2015

NO IMAGE
AVAILABLE

PP109 – Dillon Br Down – Feb 2020

Photo Point 110



PP110 – Dillon Br S – Jul 2011




PP110 – Dillon Br S – Nov 2014



PP110 – Dillon Br S – Nov 2015



PP110 – Dillon Br S – Feb 2020



PP110 – Dillon Br E – Jul 2011



PP110 – Dillon Br E – Nov 2014



PP110 – Dillon Br E – Nov 2015



PP110 – Dillon Br E – Feb 2020



PP110 – Dillon Br N – Jul 2011



PP110 – Dillon Br N – Nov 2014



PP110 – Dillon Br N – Nov 2015



PP110 – Dillon Br N – Feb 2020

Photo Point #107 (Abandoned in 2018)



PP107 – Michel N – Jul 2011



PP107 – Michel N – Jul 2015



PP107 – Michel N – Jan 2018



PP107 – Michel NW – Jul 2011



PP107 – Michel NW – Jul 2015



PP107 – Michel NW – Jan 2018



Photo Point #105



PP105 – West – Apr 2017



PP 105 – West – Jan 2018



PP 105 – West – Feb 2020

Photo Point #104



PP 104 – Dwn Strm – Apr 2017



PP 104 – Dwn Strm – Dec 2017



PP 104 – Dwn Strm – Feb 2020

Photo Point #103



PP 103 – Up Strm – Apr 2017



PP 103 – Up Strm – Dec 2017



PP 103 – Up Strm – Feb 2020